Notice of Violation Pursuant to Requirements of the Resource Conservation and Recovery Act (RCRA)

TO: Facility Name: Jacam	Vanufac	storing 2013 LC-Morth		
Address: 1656 Av	Ronsol	5 67579		
EPA ID Number: KSR 209		Date: ///17-19/20/5		
	liance order (Il violations r			
1) 40 CFR 270.16	San	anima Hill over 90 olove with a same		
	540	oring HW over 90 days without a permit (+ UW lamps not containerized or labeled		
340 CFR 273,13(d)(1) + 273,14(e)		den Lab Waste Pay Contumers in Lab		
3) 40 CFR 265, 173(a)		ake a HW determination on:		
(1) 40 CFR 262,11				
		Chloroform labouste		
		Panna Booth filters Loftover Pana Prior to Dry		
		2 draw of ald Dissel Food Pallin 1975 See 1998 2		
		Aerosol Drained Liquid		
	\biggs_{\pi}	@ Sump Waste @ Blog #1		
	A	8 Pails of Unknown wish. CRU25 + I drum @ Bldg #3		
	(h)(h)	12 old drums labed as Diesel Frel		
include a description of all corrective The response should be submitted to: U. A.	S. Environmoon Minner			
If you have any questions about this 1913-551-7049, o	Notice or wis or <u>Koviv</u>	sh to discuss your response, you may call me at D. Snowden (Compliance Officer) at		
This Notice prepared by A	er les	Masure Date: 11/19/15		
The undersigned person acknowledg	es that he/she	he has received a copy of this Notice and has read same.		
Sig	inted Name: gnature: tle:	H.DANIEL STAFFORD Date: 11/19/15		

A Hachment 5 Page 1 of 2

Notice of Violation Pursuant to Requirements of the Resource Conservation and Recovery Act (RCRA)

Address: 165 6 Avenu	anufacturing 2013 LLC-North
EPA ID Number: KSR 209	1500505 67579 1006924 Date: 11/17-19/2015
This notice does not constitute a complia	tion to the following areas of noncompliance with state and federal regulations. ance order (Administrative Civil Complaint) pursuant to Section 3008 of RCRA violations resulting from the the inspection.
Citation	Description of Violation
	(i) Speny Raga and Absorbent Piga (i) Spent Kitty Litter (k) Spill on N side of Bldy S
	(j) Spent Kitty Litter
	(k) Spill on N side of Bldy 5
and the second s	(L) PPE (M) Unlabeled Fail in Blog#7
	a) South Plans - Pallet of material in Pole Rown
	(1) South Plant-Pallet of material in Pole Para (1) South Plant-Blue drum of Opo 15/8 with bulging but
	MR 이 1.1() : [15] : [15] : [15] : [15] : [15] : [15] : [15] : [15] : [15] : [15] : [15] : [15] : [15] : [15]
)40 CFR 265.52(e)	Undate contingency plan to include equipment list descriptions for Dan and Cindy Documentation of HW related training completed
140 CFR 265, 16 (d) (2)	Unders job descriptions for Dan and Cindy
40 LFK 265, 16 (d)(4)	Ducumentation of HW related training completed
	The second section of the second section of the second sec
include a description of all corrective ac The response should be submitted to:	response within 14 calendar days of receipt of this notice. Your response should ctions taken and/or a schedule for completing the necessary corrective actions. Environmental Protection Agency, Region VII O Minne Sota Avenue ansas City Kanas 66 10 1
	M. Dedriel Newsome
If you have any questions about this No. 913-551-7049, or 913-551-7022.	otice or wish to discuss your response, you may call me at Nevin D. Snawen (Compliance Officer) at
This Notice prepared by 45 adm	M Newsone Date: 11/19/15
	Market Date: 11/19/15 s that he/she has received a copy of this Notice and has read same.

Attachment 5 Page 2 of ?